

MATERIAL KEY:

- 1 - 40x40x2 SS box
- 2 - 40x40x6 SS Angle
- 3 - 75x25x2 SS Angle (tray holder)
- 4 - SS plate, to be flush with bottom of frame, hole size to suit M10 rawlbolts.

